



Supply To MCB's

Supply from Enemalta meter

IMP: Fuses are required between Main MCB and SPD if Main Isolator has a tripping value greater than 125A.

Date Drawn: 17/05/2021	Design by: LD		Three Phase SPD + OVR	DRW Number:
Date Revision 1:	Drawn by: LD		<p>Wiring Diagram Circuit</p>	Pg. No:
Date Revision 2:	Scale: Nil			
Date Revision 3:	Ref No:			

